HOP DRAIN

Board of Determination

Ottawa County Water Resources Commissioner

Joe Bush

November 19, 2019






Outline

- Location
- Background
- Drain Condition/Inspection
- District Boundary
- Questions

Location



Hop Drain



Background/History

- Open Drain System
- Watershed 800 Acres/1.26 Sq. Mi.
- Serves a Mixture of Land Use Types
 - Undeveloped/Forest
 - Agricultural

Outlets to the Beldt Drain



General Condition – Facing Downstream



Port Sheldon St. – Downstream Face



Port Sheldon St. – Culvert



6285 72nd St. – Facing Upstream



6285 72nd St. – Upstream Face



Bend to the East at 72nd St.



Facing Upstream of Bend at 72nd St.



Bingham St. Culvert – Facing Downstream




Bingham St. Culvert




Vegetation Upstream Bingham St.



Private Crossing – Facing Upstream



Scour Hole / Undersized Crossing – Facing Downstream



Joint / End Failure



Joint / End Failure




Van Buren St. – Downstream Face



Van Buren St. – Downstream Face



Van Buren St. – Facing Downstream




Van Buren St. – Facing Upstream




Van Buren St. – Facing West



Localized Flooding



Shed – High Water Mark



Shed – High Water Mark




Drain Condition


Overall Condition

- Areas Of Erosion On Channel Banks Along
 72nd Street Steep Slopes
- Vegetation Is Beginning To Encroach On The Channel
- Culverts Several Steel Culverts Are Approaching The End Of Their Service Life
- Several Culverts Are Undersized
- Exposed Joints on Concrete Culvert Limit Capacity
- Localized Flooding Van Buren Street


Existing Drainage District Boundary




Field Checking Example




Field Checking Example




Field Checking Example



Existing & Proposed Boundaries



Proposed Drainage District Boundary



Ottawa County Water Resources Commissioner

Joe Bush 616-994-4530

Paul Forton, P.E. 989-529-8612 paulf@spicergroup.com

