Chad Meints Chief Deputy

12220 Fillmore, Room 141, West Olive, MI 49460

Ph.(616) 994-4530

FAX (616) 994-4529 Email waterresourcescommissioner@miottawa.org

NOTICE OF DRAIN MAINTENANCE

February 26, 2019

Recently an inspection was made of the **Beaver Dam of Allendale Drain** which runs through or near your property. The result of the inspection was that maintenance including brush, tree, and sediment removal is necessary. During the next two weeks, contractors will be walking the drain/drainage easement to prepare their bid for the work. A follow-up letter will be sent out once we know who the contractor will be and their schedule.

As soon as possible, please mark any and all structures in the drainage easement (invisible dog fences, underground sprinkling, sump lines/tile outlet, property corner pins, etc.). Contractors will not be held responsible for anything damaged that was unmarked.


Your cooperation is always appreciated in these matters. Should you have any questions, concerns, or input that you would like us to consider, feel free to contact us at (616) 994-4530 or email waterresourcescommissioner@miottawa.org.

Thank You,

Chris Machiela **Drain Inspector**

Allendale Township CC:

Encl: Map of the proposed drain maintenance area (on the back of this letter)



250

500 Feet

Ottawa County Water Resources Beaver Dam of Allendale Drain Clean Out

ection Town Range:Allendale Sec 20/29
Soil: Plainfield Sand
Length:1300 ft Cleanout
Drain length:9560 ft
Easement:50ft or SG total